

## Waste Water Treatment Facility Repairs 30-Year-Old Pipe with DuraWrap Carbon Fiber Pipe Wrap System

**Client:** Waste water treatment facility


**Location:** Mid-Atlantic Region of the U.S.

**Problem:** Leaking 30-year-old sewage intake pipe.

**Solution:** Manually prepared pipe's surface, repaired problem areas with *METALCLAD DurAlloy* and reinforced pipe with *METALCLAD DuraWrap Carbon Fiber Pipe Wrap System*.

**Cost:** \$4,000 total turn key project.

**Savings:** Full pipe replacement would cost about \$300,000.



The Problem



Surface Prep.



DurAlloy Repairs



DuraWrap Primer



Finished DuraWrap System

6 Platinum Court • Medford, NY 11763  
Toll Free: 888-4-ENECON • Phone: 516-349-0022 • Fax: 516-349-5522  
[www.enecon.com](http://www.enecon.com) • [info@enecon.com](mailto:info@enecon.com)