ENECON® NEWS



ENECRETE WP, WS & DuraQuartz

Ideal for Elevator Pit Renovation Projects

Many elevator pits suffer from similar problems: hydrostatic water pressure often creates a wet and unpleasant condition that raises safety as well as environmental concerns for maintenance engineers.

After

Before

has been very successfully used to repair and fill all cracks in the concrete, followed by ENECRETE WP & WS to plug and seal out future water infiltration caused by hydrostatic pressure.

The entire repair and reclamation of a typical elevator pit can be completed in just one da at a fraction of the cost associated with conventional concrete restoration procedures.

ENECRETE WP, WS & DuraQuartz provide the unconventional solution to a very common facilities maintenance are blem.

700 Hicksville Road • ENECON Center Suite 110 • Bethpage, New York 11714
Toll Free: 888-4-ENECON • Phone: 516.349.0022 • Fax: 516.349.5522
Website: www.enecon.com • Email: info@enecon.com