


US Air Force Base Workshop Floors Repaired and Resurfaced With ENECLAD FPS 2000



These workshop floors had seen better days. Constant use and abuse had contributed to the deterioration. A long-term yet cost effective repair was needed and the ENECON Mid Atlantic Engineering Team was called in to provide the products and application expertise necessary to completely recondition these floors.

the ENECRETE SPS (Self Priming Screed) system. A final coat of ENECLAD FPS 2000 was then applied to completely seal the shop floors and provide for a slip resistant surface that will provide many years of trouble-free performance in this very demanding environment.

The workshop floors were first 'blast-tracked' and then repaired and primed with



700 Hicksville Road • ENECON Center Suite 110 • Bethpage, New York 11714
Toll Free: 888-4-ENECON • Phone: 516.349.0022 • Fax: 516.349.5522
Website: www.enecon.com • Email: info@enecon.com