ENECON® NEVIS









Location

A local municipal water authority in South Carolina.

Problem

Years of neglect as well as old failed coating systems had caused these concrete structures to show signs of degradation.

Solution

Clean and prepare all concrete surfaces. Then apply 2 coats of ENESEAL HR.

Both structures were power washed to remove dirt and any old failed coatings were manually removed with a scraper. Not only does ENESEAL HR provide a clean uniform look, it will provide heat refraction properties and protect the concrete from any future atmospheric corrosion.







