

Russian Candy Factory Floor is Rehabilitated Using DuraQuartz, P4C & ENECLAD FPS.



Client: Russian candy factory.

Problem: Concrete floor was severely cracked creating a safety hazard and potential damage to finished goods.

Solution: The floor was manually prepared and all loose material was removed. ENECRETE DuraQuartz was used to repair all cracks and voids. The floor was primed using CHEMCLAD P4C. Two coats of ENECLAD FPS were then applied. The client was delighted with the results.



6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON[®] (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com