



Geothermal Power Plant Uses CHEMCLAD[®] SC to Stop Corrosion on Waste Removal Trailers

Client: Geothermal power plant located in California.

Problem: Corrosion to the steel beds of the trailers used to transport geothermal waste product (very salty brine mineral debris) to waste facilities.

Solution: Various conventional paints and liners had been used over the years and all of them had failed very quickly.

The trailer beds were grit blasted and two coats of CHEMCLAD SC were sprayed onto the 550 sq ft beds.

The power plant was so pleased with the results that work on 12 more trailers has been scheduled.



6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON[®] (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com