ECON REVS







Client: **Power Plant**

Location: Chile



Problem:

Concrete containment area was suffering from chemical attack and corrosion after prolonged exposure to oil and fuel spillage.

Solution:

After removing contaminated concrete and thoroughly cleaning, ENECRETE DuraQuartz was used to repair the concrete walls.


CHEMCLAD SC was then used to protect the concrete from future corrosion.

Coverage Area:

55 m² / 592 ft²

Cost:

\$8,000 (\$5,000 in ENECON products & \$3,000 in labor).





6 Platinum Court • Medford, NY 11763 Toll Free: 888-4-ENECON • Phone: 516-349-0022 • Fax: 516-349-5522 www.enecon.com • info@enecon.com