

International Pharmaceutical Company Stops Leaks with ENESEAL



A major pharmaceutical research company had a recurring problem with water leaking from the penthouse equipment room to the critical laboratories below.

The equipment room contained numerous pieces of air handling equipment. The ducts leading to











ES-016



and from this equipment formed an easy path for spillage to find its way to lower floors.

ENESEAL HR was chosen to provide a flexible seal and bridge the gaps between the ducts and the concrete floor.

Applied as a liquid, ENESEAL HR conformed to the irregular shapes of the brackets supporting the ductwork and the ducts themselves. Tape and insulating boards were used to smooth the most irregular shapes or where insulation was loose or missing.

700 Hicksville Road • ENECON Center Suite 110 • Bethpage, New York 11714 Toll Free: 888-4-ENECON • Phone: 516.349.0022 • Fax: 516.349.5522 Website: www.enecon.com • Email: info@enecon.com