
## ELECON® NEVS









Client:

**Dairy Product Manufacturer** 

Location: Chile

Problem:

Large hard water tank suffering from interior and exterior corrosion.

## Solution:

The interior of the tank was grit blasted to a white metal finish then protected with 2 coats of CHEMCLAD SC.

After mechanically cleaning and power washing, the exterior of the tank was protected with 2 coats of ENESEAL CR.

Coverage Area: 150,80 m<sup>2</sup> / 1623.2 ft<sup>2</sup>

## Cost:

\$40,000 (\$24,000 in ENECON products & \$16,000 in labor).

## Savings:

Replacing this tank would cost upwards of \$150,000.

6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com