



## Town Park Uses DuraQuartz & ENESEAL to Repair & Protect Concrete Ceiling



**Client:** Parks and Recreation Department in New York State.

**Problem:** The park's entrance ceiling was showing signs of water damage, spalled concrete, exposed rebar and missing failed coating. The Town was concerned that loose concrete could create a safety issue for park users.

**Solution:** A combination of power washing and hand grinding was used to thoroughly clean the surface and remove any loose concrete. Any exposed rebar was coated with **ENESEAL CR** and all damaged concrete areas were repaired with **ENECRETE DuraQuartz** with *light weight aggregate*. **ENESEAL HR** was used as a final topcoat.



6 Platinum Court • Medford, NY 11763  
Toll Free: 888-4-ENECON • Phone: 516-349-0022 • Fax: 516-349-5522  
[www.enecon.com](http://www.enecon.com) • [info@enecon.com](mailto:info@enecon.com)