

One of the Largest Oil Companies in the Philippines Selects ENESEAL CR to Fight Steel Corrosion



This large gasoline tank located at one of the largest oil companies in the Philippines had been suffering from severe corrosion.

Previously the tank had been coated with an epoxy enamel that would last less than one year and would require touch-up

applications routinely.

The engineers called in the ENECON Philippines Field Engineering Team for help. It was decided that the tank would be cleaned with a combination of power washing and hand tools since grit blasting was not possible.

A two coat system of ENESEAL CR was then applied to provide long term corrosion protection.

Tank Dimensions: Diameter - 21.0 meters, Height - 12.8 meters.

Amount of Project: \$70,000.

6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON[®] (888-436-3266) • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com