




## ENECON Italia Repairs Damaged AC Condenser with CeramAlloy on US Naval Vessel



The Regional Contracting Center for the US Navy in Naples, Italy, awarded a repair contract for an AC Condenser repair to be performed in Augusta Bay, Sicily. For logistical reasons, the ship was moved to the island of Palma de Mallorca during the Easter week.

ENECON Italia brought equipment and personnel to the island and in three days repaired both ends of the AC Condenser and the water boxes according to the approved ENECON Specification / Procedure for tube sheet repairs.

