

METALCLAD CeramAlloy Stops Corrosion on Power Plant Heat Exchangers



Client: 550 Megawatt Natural Gas Power Plant.

Location: California

Problem: Accelerated corrosion of 2 year old heat exchangers (8 units) due to prolonged exposure to recycled water.

Solution: 40+ mil, 2 coat application of a METALCLAD CeramAlloy CL+AC system.

Cost: \$66,000 product only.



6 Platinum Court • Medford, NY 11763
Toll Free: 888-4-ENECON • Phone: 516-349-0022 • Fax: 516-349-5522
www.enecon.com • info@enecon.com